Checklist for Remote workstation

Before setting up your workstation, please check to see that you have the following:

1. **Wyse terminal** (color or size may vary)

Wyse terminal (old)   OR   Wyse terminal (new)

2. **Power supply** for Wyse and **Ethernet cable –** 1 end connects to Wyse and other to router

Power supply for Wyse terminal   Ethernet cable (color may vary)

3. **2 x Monitors; 2 x power supplies for monitors** (may vary)

Monitors x2 (model & stand vary)   Power supply x2 (for monitors)

4. **DVI cable** (connects to Wyse and **left monitor**); **VGA cable** (connects to Wyse and **right monitor**). **Splitter** (connects to Wyse and to the monitors)

DVI cable

VGA cable

Splitter

5. **Mouse and keyboard** connect to Wyse terminal (may vary)

Mouse

Keyboard

Final workstation setup:

DVI - Left side   VGA - Right side